

**Nina Webb
394 East Pond Meadow Rd.
Westbrook, CT**

Photographs- Existing Conditions @ Driveway Culvert

1/3



No. 1 View of driveway. Culvert inlet @ right, culvert outlet @ left. May 2020



No. 2 View of culvert inlet. May 2020



No. 3 View of culvert outlet. May 2020



No. 4 View of outlet endwall from driveway. May 2020



No. 5 View of inlet endwall and culvert. April 2020



No. 6 View of culvert at inlet looking down gradient. Note deterioration of metal.